

Review Sec. Cor.  $\frac{53}{52}$  |  $\frac{510}{511}$  T245 RIW

Fd. 211 four ORIGINAL BTs alive & IN good condition & 2 stones with NO MARKS ON them. Distances to BTs WAS apparently taken on slope FROM the face. -

24" Now 39" cedar N. 65° E. 29° ft (slope)  
Shows " T2 RI 52 BT" on partially healed SCAR.

24" Now 29" Fir S 45° E. 31 1/2 ft. (Slope)  
Shows good SCAR.

24" Now 30" Fir S. 72° W. 33° ft. (slope)  
Shows good SCAR.

30" Now 36" Fir N. 8 1/2° W. 29° ft. (level)  
Show very good SCAR.

We set 1" I.P. & BRASS cap MKd.

"COUNTY SURVEYOR'S OFFICE 1965

T245 RIW  $\frac{53}{52}$  |  $\frac{510}{511}$  " We MARK NO New

BTs - This cor. lies on steep West slope approx. 300° ft. East of Road.

June 15, 1965

V.R.T.  
T.C.

~~ART Ray~~  
+X

C.S. File No. 52/98-34