

Renew  $\frac{1}{4}$   $\frac{526}{535}$  T245 RIW

See Ren. # 37 of Dec. 1964, we find  
Both Ren. B.T.s & one orig left.  
as follows -

ORIG,  $\frac{1}{6}$ " cedar N.  $25^{\circ}$  E. 17  $\frac{3}{4}$  ft.

alive - shows good scar. sets in edge  
of fill for new logging Rd.

Ren. B.T. 6" W. Fir (not Hem) N.  $72^{\circ}$  E. 35  $\frac{3}{4}$  ft.

alive at foot of fill - scribe visible.

Ren. B.T. 8" Hemlock S.  $26^{\circ}$  W. 8  $\frac{1}{4}$  ft.

alive - scribe visible - on upper side of Rd.

actual cor. falls in Road. - set  $\frac{3}{4}$ " I.P.

flush with road surface & witness

cor. 70 ft. west. set 1" I.P. &

BRASS cap mkd. "COUNTY SURVEYORS

OFFICE 1966 T245 WIT. COR.  $\frac{1}{4}$

$\frac{526}{535}$  RIW 70 FT. E. TO COR." & MK

New B.T.s -

13" D. FIR N.  $7^{\circ}$  E. 12  $\frac{5}{8}$  ft.

Mkd. "WC  $\frac{1}{4}$  526 CS BT"

18" D. FIR S.  $1^{\circ}$  W. 3  $\frac{8}{8}$  ft.

Mkd. "WC  $\frac{1}{4}$  535 CS BT"

Nov. 14, 1966

JRT

JH

B.W.



~~Handwritten signature or scribble~~

#65  
to  
D.H.S.W.D.

C.S. File No. 52/42-49