

Review  $\frac{1}{4}$  518/517 T245 RIW  
Fd. 1962 C.S. BRASS COP & BT.  
properly MKd (see Rev. #24) 2-  
21" D. FIR N. 23° E. 24° FT.  
2 live-face pitched over.

Both orig. BTs now turned out  
& slid down very steep South East  
slope. We MK. New BT. as follows -  
28" D. FIR S. 40° W. 44<sup>8</sup> FT.  
MKd. " $\frac{1}{4}$  518 CS BT"

This cor. lies on steep S.E.  
slope.

June 15, 1967

V.R.T.  
J.H.  
D.W.

*V.R.T. May*

P11

X

for B.M.)

C.S. File No.

52/42-55

ON 11/55