

Renew Sec. Cor. <sup>526/525</sup> 535/536 T245 R2W

Fd. 1951 Cor. BRASS CAP firmly set  
& properly MKd. at cor. & following B.T.s

OB.T. 28" FIR N. 60° E. 23 1/2 ft.

2 live - show scar -

OB.T. 20" Hemlock S. 57° E. 35° ft.

2 live show scar -

1951-12" Hemlock N. 30 1/2° E. 25 1/2 ft.

2 live - scribe visible on unhealed  
Blaze

20" FIR. S. 79° E. 44 1/2 ft.

2 live - Blaze pitched over.

No B.T.s West of Line Due  
To Refw. clearing for Road.  
we mk. new B.T.s -

7" Hemlock S. 30° W. 45 1/2 ft.

Mkd. "T245 R2W 535 CS BT"

8" D. FIR N. 60° W. 41° ft.

Mkd. "T245 R2W 526 CS BT"

This cor. lies on steep west  
slope 150 ft. East of Rock Creek  
Access Road.

July 3, 1962

#38

*(Handwritten signature)*

U.R.T.  
D.W.

C.S. File No. 52/4254