

Renew  $\frac{1}{4}$  535 | 536 T245 RIW

Fd. CRT. 25 follows -

orig. 18" Now 34" FIR N. 75° E. 24 $\frac{1}{2}$  Ft

Now sawed stump - we open & find

"BT" scribe & Reverse - we find NO

Trace other orig. B.T. OR COR. STONE

called for. Set 1" I.P. & BRASS COP

Mkd. "COUNTY SURVEYOR'S OFFICE

1967 T245  $\frac{1}{4}$  535 | 536 RIW" &

Mk. New B.T.s -

14" Cedar N. 75° W. 21 $\frac{1}{2}$  ft.

Mkd. " $\frac{1}{4}$  535 CS BT"

12" Hemlock stump S. 31° E. 9 $\frac{1}{2}$  ft.

Mkd. " $\frac{1}{4}$  536 CS BT"

(No live trees east of line due to  
clearcut logging) - This cor. lies  
on very steep northerly slope.  
approx 270 ft. S. of canton creek.

Oct 11, 1967

V.R.T.  
J.H.  
V.P.

V. R. Gray

72 P.K. J.W.B.

C.S. File No.

52/42-58