

RENEW $\frac{1}{4}$ COR. 22/23 T31SR3W

FOUND - 1 1/2" I.P. AT COR. E BAT 4

BTTS AS RECORDED BY PRICE
2 2" NOW 2 4" R. FIR 55 1/2 W 15 1/8
SHOWS SCRIBING ON BADLY BURNED
FACE. $\frac{1}{4}$ E BT NOW STUMP

NEW BTTS.

DESCRIBE 2 4" R. FIR 55 1/2 W 15 1/8
 $\frac{1}{4}$ S 22 CS BT

2" R. FIR BEARS NG 1 1/2 E 43.7
SCRIBED $\frac{1}{4}$ S 23 CS BT

~~+~~ * NOTE - ROAD BEARS WITHIN 100'

RENEW $\frac{1}{4}$ COR. 27 T31SR3W
3+

FOUND - 2" I.P. AT COR. 40" R. FIR

N46 1/2 W 59 NOW DOWN SHOWS
SCRIBING. 30" R. FIR NOW STUMP
S.W. SHOWS SCRIBING

NEW BTTS.

11" R. FIR BEARS S B E 22 P
SCRIBED $\frac{1}{4}$ S B E CS BT

6" R. FIR BEARS NG 9' E 33.5
SCRIBED $\frac{1}{4}$ S 27 CS BT

JUNE 6-63 J. B.
VAR 20 1/2 M. D.
8 3

~~+~~ * OVER $\frac{1}{4}$ S 27/826
FA. bay C. S. File No. 52/63 1/3

DIETZEN NO. 385-6