

Renewal

S 15 / S 14

T 315 R 3W

Found:

$\frac{1}{2}$ I.P.P. & Stone

37" P.F. Stump S 34 E 9² 5 BT
Shows good scars.

10" Casky Now 10" N 67 W 31⁶ 0 BT
I find this bearing to be N 69 W

4" Fir S 72 E 25⁰
No trace of this tree.

6" Fir Now 8" S 54 W 18⁶
Shows good scars

8" Fir Now 10" N 64 W 19²
Shows good scars

9" Fir Now 11" N 28 W 33⁸
Shows good scars

Renewed:

along side of $\frac{1}{2}$ " I.P.P.
set Brass cap at $\frac{1}{4}$ Cox Mark

County Surveyors Office

T 315 R 3W

$\frac{1}{4}$ S 15 S 14

19 65

Now Bearing tree:

6" Fir S 89 E 39⁶

Scribed T 314 R 3 BT

(Renewal # 62)

12-22-65

[Handwritten signature]

+ X #132

C.S. File No. 52/63-31

DIETZEN NO. 385-6