

Renewal

31 | 32
6 | 5

T315 R3W
T325 R3W

Found

I. Pipe at sec cor. - Rm^{10}

12" Fir snag N 76 $\frac{1}{2}$ E 33 $\frac{0}{2}$

I find this bearing to be N 49 E
Scribed "32"

14" Fir stump N 66 $\frac{1}{2}$ W 109 $\frac{11}{2}$

I find this to be N 65 W 110 $\frac{10}{2}$
Scribed 531 BT visible

15" Fir S 40 W 223 $\frac{1}{2}$

gone

36" Fir S 22 E 59 $\frac{1}{2}$

I find this to be S 20 E
C.B.T. Bark Scribed 1374
other points remaining visible

Renewal

along side of I pipe
Set Brass cap at sec cor. M&R

County Surveyors office

T315

31 | 32
56 | 50

T325

1960

New Bearing Trees

15" Fir S 12 E 31 $\frac{1}{2}$

Scribed T 325 R3W S 6 C S BT

9" Pipe S 35 W 24 $\frac{1}{2}$

Scribed 56 C S BT

6" Pipe N 39 W 17 $\frac{1}{2}$

Scribed 581 C S BT

20" Fir N 16 W 96 $\frac{1}{2}$

Scribed T 315 R3W S 31 C S BT

1-6-66

+ X #134

C. S. File No 52/657 45

DIETZEN NO. 385-6