

Renewal

530 | 529
531 | 532

T 315 R 3W

Fouling

1 1/2 Iron P.P.

36" Fir NW 7 1/2" S 35 E 11 1/2

Shows good scar

12" Cedar Down S 75 W 5 1/2

14" Cedar NW 2 1/4 N 17 1/2 E 17 1/2

Parts of scribing visible

16" Fir Wind Fall N 82 E W 10 1/2

Shows good scar

Renewed:

Along side of Iron P.P.

Set Brass cap at Sec. corner 1/4 D.

County Surveyors Office

T 315 R 3W

530 | 529

531 | 532

1966

New Bearing Tree

15" Douglas Fir S 87 W 14 1/2

Scribed T 315 R 3W S 91 CS BT

13" Douglas Fir N 4 W 82 1/2

Scribed: T 315 R 3W S 90 CS BT

(Renewal # 16)

1946

1-12-66
J. C. B.
F. M. G.

#137

52/63-52

DIETZGEN NO. 385-6