

Renewal

534  
53

T315 R321  
T325 R321

Found:

Iron Pipe at  $\frac{1}{2}$  cor

12" D. Fir New seed N39 $\frac{1}{2}$  E 102  
Scribe Visible  $\frac{1}{2}$ "

10" Fir New Blot Down S71 $\frac{1}{2}$  E 12 $\frac{3}{4}$

Renewal:

Along side of Iron Pipe  
Set Brass cap at  $\frac{1}{2}$  cor MAD

County Surveyors Office

T315

$\frac{1}{2}$   $\frac{534}{33}$  R  
W

T325

1966

DIETZGEN NO. 385-6

New Bearing Trees:

10" D. Fir Scribed  $\frac{1}{2}$  34 N20W 23 $\frac{1}{2}$   
CS BT

9" W. Fir Scribed  $\frac{1}{2}$  3 S71 $\frac{1}{2}$ W 10 $\frac{1}{2}$   
CS BT

1-26-66

(Renewal #13)

#168

447-T32

C. S. File No. 52/63-69