

Renewal

S33 | S34 T313 R3W
54 | 53 T325 R3W

Found:

1" Iron Pipe MK Sec cor.
30" Fir Now 31" S43E 15 1/2
Has been opened but pitched over
Distance to the Face

10" Chinquapin Now 20d 32 1/2 W 14 1/2
Scribe visible "S4 BT"

12" Fir Now 19" N75 W 20 1/2
Shows good Seal

12" Hemlock Now Blaw Now N59E 29 1/2
Scribe visible "S34 BT"

Renewed

Along Side of Iron Pipe
Set Brass cap at Set cor MKP.

County Surveyors Office

T313
S33 | S34 R
54 | 53 S
T325 W
1966

New Bearing Trees

8" P. Fir S60 1/2 W 42 1/2
Scribed T325 R3W S 1 C3 BT

13" P. Fir N35 E 52 1/2
Scribed T313 R3W S 34 C3 BT

This cor. lies on top of small side
ridge in bottom of Ravine.

1-26-66

[Handwritten signatures]

(Renewal #25)

X #167
#46-132

C. S. File No. 52/63-20

DIETZGEN NO. 385-G