

Renewal

530
531
535
536

T365 R393W

Found:

30" Fir NOW 30" N35W 28°
Shows Scribe Marks

16" Fir NOW DOWN N45E 12°

OBT:

30" Fir NOW stump S18W 53°

30" Fir NOW DOWN 530E 23°
Shows Scar,

No Trace of Iron Pipe
Renewed.

St Brass cap at Sec. Cor 11th,
County Surveyors Office

	T365	
R	527	R
3		2
W	536	W1
1966		

New Bearing Tree

8" Chinquapin S60W 31°

Scribed T313 N3W 536 CS DP

A-15-66

JWM
JWF
JCB

Renewal #35

187.23W
139.731-2W

*O

OK J.W.B.

C.S. File No. 52/63.09

DIETZGEN NO. 385-6