

Renew Sec Cor  $\frac{54}{59} \frac{53}{510}$  T26S R1W  
Fd. Cor. Stone tipped over & obts  
as follows -

Orig. 40" Now 41" Fir N.  $22^{\circ}$  E, 86<sup>5</sup> ft.  
(level) Now snag - scribe visible on  
unhealed Blaze -

Orig. 28" Now 32" Fir S.  $49^{\circ}$  E, 45<sup>5</sup> ft.  
(slope) - alive - shows good scar wet sq.

2130 Mound of stone as described  
West of cor. - at cor. point set  
in mound of stone, 2 1" I.P. & Brass  
cap MKd. "COUNTY SURVEYORS

OFFICE 1970 T26S  $\frac{54}{59} \frac{53}{510}$  R1W"  
MK. New B.T. -

36" D. Fir N.  $25^{\circ}$  E, 106<sup>5</sup> ft.  
MKd. "T26S R1W S3 CS BT"

No Trees available in sec. 5  
& 9 due to Solid Rock Bluffs  
This cor. Lies at top of Bluff 30 ft.  
high. Water fall approx 200 ft  
high. Bears N.  $83^{\circ}$  W. approx. 400 ft.  
Dist.

March 4, 1970

#43

W.R.T.  
J.G.H.  
J.B.P.

O.K.  
J.W.B.

C.S. File No. 52/77-524