

514/513

Renew Sec. Cor 523/524 T285 R8W

Fd at Cor. 2 of the 4 BTs Recorded
in Renewals #6/c #8 Both are dead.

Other BTs are turned out & slid down
hill. also Fd. No trace of BRASS Cap.

20 8" FIR S. 40° W. 225 Recorded 25
S. 30° W. Shows scribe marks is a snag.

The 15" FIR N. 85° E. 17° ft is a stump
& has a healed over face visible on top.

Set for Cor. 2 1" I.P. & BRASS
Cap MKd. COUNTY SURVEYOR'S OFFICE
1964 T285 R8W 514/513 " #New BTs -
523/524

9" D. FIR S. 53° W 595 ft.

Mkd T285 R8W S 23 CS BT

14" D. FIR N. 55° E 144 ft.

Mkd T285 R8W S 13 CS BT

10" D. FIR S. 8° E 565 ft.

Mkd T285 R8W S 24 CS BT.

No Tree available to N.W.

Sept 9, 1964

V.R.T.
M.D.
J.B.

~~R. Frank~~

+XO ✓

C. S. File No. 52/79-14