

T 22 S R 8 W

$\frac{1}{4}$  S | S  
28 | 27

FD. 18" FIR (NOW 27" DIAM.)  
WEST 20 $\frac{1}{2}$  FT. UPROOTED & DOWN.  
THIS TREE HAD BEEN OPENED  
BEFORE IT FELL (FACE DOWN).  
TRACES OF SCRIBING VISIBLE.

FD. 16" FIR (NOW 24" DEAD SNAG)  
N 85° E 35 $\frac{1}{2}$  FT. SHOWS GOOD SCAR.  
DID NOT CHOP OPEN.

AT COR. SET IRON PIPE WITH  
BRASS CAP MKD. "COUNTY SURVEYOR'S  
OFFICE 1961 T 22 S R 8 W  $\frac{1}{4}$  S | S  
28 | 27"

BLAZE & SCRIBE 2 NEW TREES:  
18" FIR N 42° W 32 $\frac{1}{2}$  FT. MKD.  
" $\frac{1}{4}$  S 28 CS BT."  
15" FIR N 20° E 44 $\frac{1}{2}$  FT. MKD.  
" $\frac{1}{4}$  S 27 CS BT"

NOTE - THIS CORNER LIES ON A  
STEEP WEST SLOPE ABOUT 100 FT.  
WEST OF A RIDGE TOP.

JUNE 8, 1961

M. G.  
C. P.

Milo E. Godfrey

C. S. File No.

52/80