

REN. T26SR6W

COR.
SECS.

4/3
9/10

FD. STUMP HOLE & ROTTEN, DOWN
OAK S 27 $\frac{3}{4}$ ° E 71 $\frac{1}{2}$ FT. - OPENED &
FD. GOOD REVERSE SCRIBING ON OLD
SLAB.

FD. STUMP HOLE & ROTTEN REMAINS
OF OLD OAK S 71° W 25 $\frac{1}{2}$ FT. - ALL
REVERSE SCRIBING VISIBLE ON OLD
SLAB.

FD. ROTTEN REMNANTS OF OLD
MADRONE N 37° W (NOT N 70 $\frac{1}{2}$ ° W) 28 $\frac{1}{2}$ FT.
- OVERGROWTH OF 2 OLD AXE SCARS
FD., BUT NO SCRIBING.

NO TRACE FD. OF ORIG N.E. TREE
AT COR. SET IRON PIPE WITH
BRASS CAP MKD. "COUNTY SURVEYOR'S
OFFICE 1964 T26SR6W $\frac{54}{39}$ / $\frac{53}{S10}$ "

BLAZE & SCRIBE NEW TREES:

18" DOUG. FIR S 10° W 58 $\frac{1}{2}$ FT.
MKD. "T26SR6W S9CSBT"

17" DOUG. FIR N 61° W 17 $\frac{1}{2}$ FT.
MKD. "T26SR6W S4CSBT"

11" DOUG. FIR N 11° E 21 $\frac{1}{2}$ FT.
MKD. "T26SR6W S3CSBT"

14" DOUG. FIR S 50° E 2 $\frac{0}{2}$ FT.
MKD. "T26SR6W S10CSBT"

JUNE 10, 1964

Milo E. Godfrey

M.G.
W.S.
M.D.

+ R ✓

M.S. 52/87 $\frac{2}{1}$