

Review $\frac{1}{4}$ 533/534 T245R6W
 Fd. $1\frac{1}{4}$ " I.P. set by #11 Stewart in 1922
 & $\frac{3}{4}$ " I.R. Dropped inside - I.P. is
 Broken & Rusted Through - Stewart's
 B.T.s as follows - (see Rev. # 11)
 24" Now 24" W. F.I.R. N. 42° W. 63^o ft.
 Now only decayed Remains - No scribe Fd.
 30" Now 30" D. F.I.R. S. 66° W. 63^o ft.
 Now sowed stump - scribe MKs. visible
 on Burned & unhealed Blaze. 2^d cor.
 point set 1" I.P. & BRASS cap MKd.
 "COUNTY SURVEYOR'S OFFICE
 1969 T245 $\frac{1}{4}$ 533/534 R6W" &
 MK. New B.T.s
 8" D. F.I.R. N. 41° W. 37³ ft.
 MKd. " $\frac{1}{4}$ 533 CS BT"
 10" D. F.I.R. S. 19° E. 11⁴ ft.
 MKd. " $\frac{1}{4}$ 534 CS BT"
 Reset unrecorded I.R. along side.
 This cor. lies 2^d fence cor. - fences
 E. & S.

May 8, 1969

V.R.T.
 J.G.H.
 V.D.P.

V.R.T. Tracy

O.K.
 J.W.M.

88

C.S. File No 52/102-2