

Renewal 27 126
34 / 35 T243 86W

Found:

16" B. Oak NW 40° SE 4 E (Rec 568 1/2) 57
Shows faint scar

15" B. Oak NW Dead N 1/2 E (Rec N 1/2 E) 26 1/2
Previously open; found reverse scribble

30" B. Oak New Rotten Stump N 68 W 31 1/2
No marks found:

5W BT Down Rotten Hits Fair for
Bearing 537 1/2 W 206 1/2

Renewal

By using 3 class Distances & 1 Bearing
Set Brass cap at sec cor MAP
county Surveyors office

T243 86W

527 526
537 535

1969

New Bearing Trees:

6" W Oak S 59 1/2 E 2 1/2
Scribed T243 86W 535 CS BT

11" P. Fir N 20 E 38 1/2
Scribed T243 86W 526 CS BT

12" Laurel N 13 W 38 1/2
Scribed T243 86W 527 CS BT

18" Laurel S 79 W 23 1/2
Scribed T243 86W 534 CS BT

Note: This cap lies 10' South
of old Fence cor Fence Running
North East & West

DIETZGEN NO. 3895-6

#90 D.K. J.W.O.

9-12-69
C. S. File No. 52/100-4