

REN. T 23 S R 6 W

N  $\frac{1}{16}$  S  $\frac{1}{2}$  S  
26/25

FD. IRON PIPE WITH G.L.O. BRASS  
CAP - BULLDOZED OUT OF POSITION  
(IN FIRE TRAIL) - APPROX. 10 FT. S.W. OF COR.

FD. 8" W. FIR S  $67\frac{1}{2}^{\circ}$  E 12  $\frac{1}{2}$  FT.

SCRIBING STILL VISIBLE. TREE ALIVE &  
IN GOOD CONDITION.

FD. STUMP OF 10" FIR S  $50\frac{1}{2}^{\circ}$  W  
19  $\frac{3}{4}$  FT. SCRIBING STILL VISIBLE. STUMP  
PARTLY UPROOTED & TIPPED OVER.

AT CORNER RESET PIPE WITH  
BRASS CAP.

BLAZE & SCRIBE ONE NEW TREE:

18" DOUG. FIR N  $7^{\circ}$  W 41  $\frac{3}{4}$  FT.

MKD. "N  $\frac{1}{16}$  S 26 CS BT"

NOV. 2, 1962

M.G.

V.T.

M.S.

*Walter C. Godfrey*

~~XX~~ OV

C. S. File No. 52/102 25