

Renew Sec. Cor. ⁵¹⁰/₅₁₅ | ⁵¹¹/₅₁₄ T245 R6W

Fd. old fence cor. post that has been used for sec. cor for at least the last 60 years - There are no orig. B.T.s left - But at the locations where they should be - we find slight depressions in ground - We rerun Floyd Frears Road Tye from end of C. Rd. #73

Done in 1925 and again come out to fence cor. - To determine end of County Rd. - we use old cherry tree tied to by Frear which bears $5.32^{\circ} E.$ 485 ft. - Since old fence cor. post is set very solid and is in good cond. we set 1" I.P. & Brass cap 6" EAST of old Fence cor.

Post. MKd. "COUNTY SURVEYOR'S OFFICE 1970 T245 ⁵¹⁰/₅₁₅ | ⁵¹¹/₅₁₄ R6W"

& MK. New B.T.s -

10" W. Oak N, $63^{\circ} E.$ 403 Ft.

Mkd "T245 R6W S11 CS BT"

9" D. Fir S, $8^{\circ} E.$ 354 ft.

Mkd. T245 R6W S14 CS BT"

996

(See over)

D.K. J.W.D. 521102-82

10" D. FIR S. 54° W. 5² FT.

Mkd. "T245 R6W S15 CS BT"

10" D. FIR N. 37° W. 20⁸ FT.

Mkd. "T245 R6W S10 CS BT"

This cor. lies on westerly slope
 100 ft. East of Roadway # 161⁰
 East of creek (Record 191² ft)
 The channel of creek has been
 changed approx 30 ft. to east by
 old logging Road in bottom of
 Ravine according to Mr. Sparks,
 Landowner - Mr. Sparks also has
 lived in same place for 61 years
 and says that the fence cor.
 above described has been used
 as section cor. as long as he
 can remember -

August 12, 1970

URT
VDP

[Handwritten signature]

0-5-3
[Handwritten initials]

DIETZEN NO. 385-6