

Renew M.C.  $\frac{55}{58}$  T235 R7W

Fd. one BT. at M.C. on Right Bank as follows —

ORIG 15" now 30" oak N. 15° W. 106<sup>3</sup> ft.

Now almost Dead - previously opened & shows "S 4" we open & find "BT"

No Trace of SW. B.T. - since cor fits the E-W. Sec. line between

Sec's 5 & 8 we assume a mistake in orig. sec. number. Should be 55, we

set 1" I.P. & BRASS Cap MKd. "COUNTY SURVEYORS OFFICE 1965 T235

M.C.  $\frac{55}{58}$  R7W" & MK New BT's -

13" D. FIR S. 66° W. 110<sup>2</sup> ft.

Mkd. "M.C. 58 CS BT"

6" W. oak N. 18° W. 78<sup>5</sup> ft.

Mkd. "M.C. 55 CS BT"

This cor lies approx. 75<sup>0</sup> ft

S. of Road course SW. & N.E.

FILED

RECEIVED

Dec. 8, 1965

Ms.  
DEC 8 1965

*[Handwritten signature]*  
+X #17

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

C. S. File No. 52/125-16