

RENEW 1/4 COR. 20/21 T295R3W

FOUND - BOTH BTL AS RECORDED BY EVANS 1952. EACH BTL IS BARK SCRIBED.

WE DO NOT FIND I.P. AT COR. COR IS NEAR TOP OF CUT BANK FOR LOG. N.M.O.

SET BRASS CAP AT CORNER MARION COUNTY SURVEYORS OFFICE 1962 1/4 S 20/21 T295R3W

NEW BTL  
16" R. FIR BEAMS N 83° E 21.5'  
SCRIBED 1/4 S 21 C S B T

~~10~~

RENEW 29/28 T295R3W

FOUND - PIPE & BOTH BTL AS RECORDED BY THOMPSON. LAUREL TO SET NOW DOWN & PIPE OUT OF GROUND RESET 3/4" I.P. AT COR & SCRIBED NEW BTL.

9" CEDAR BEAMS N 67° E 16'  
SCRIBED 1/4 S R 8 C S B T

OCT 23 - 1962  
L.H.P.  
B.S.

FILED VAR 20E  
RECEIVED

OCT 25 1962

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

~~10~~

C.S. No. 52/125 66

DIETZEN N. O. 389-6