

RENEW SE COR 36 T29S R3W

FOUND - BOTH ORIG. BTS. \$

COR. TREE ALL AS RECORDED.

ORIG. 15" NOW 20" FIR N45°W

2.6' SHOWS GOOD SCAR FACE

MAY BE ROTTED I. RESCRIBE

THIS BT 536 T29S R3W C&BT

+XO ✓ ✓

RENEW $\frac{30}{31} \frac{29}{32}$ T29S R3W

FOUND - ORIG. 10" NOW 12" ROTTED
STUMP SHOWS SCRIBING "BT:"
S65°W 25.1'. WE ALSO FIND STUMP
HOLE OF NE BT, \$ ORIG. 10" NOW
20" FIR N10°W 22.3' NOT 190° SHOWS
GOOD SCARS. ORIG. SE BT NOT FD.

SET BRASS CAP AT CORNER MKD.
COUNTY SURVEYORS OFFICE 1962

$\frac{530}{531} \frac{29}{32}$ T29S R3W

NEW BTS.

58°R. FIR BEARS S 30° W 34.2'
SCRIBED 531 T29S R3W C&BT

12" CEDAR BEARS S 12° E 35.9'
SCRIBED 532 T29S R3W C&BT

RESCRIBE ORIG. ~~NW~~ 20" R. FIR N10°W
22.3' S30 T29S R3W C&BT

12" W. FIR BEARS N 44° E 3.4'
SCRIBED T29S R3W S 29° E 5 BT

J. B.
M. D.
B. S.

DEC. 17 - 1962

OX ✓

C. S. File No. 52/126-90