

Review $\frac{1}{4}$ 53 | 52 T295 R4W

Fd. one B.T. (original) 25 follows -

24" Now 32" FIR N. 55° E. 12' ft.

original BARK scribe " $\frac{1}{4}$ 5" in good

condition & "BT" scribed in wood 28

Recorded in Renewal # 169. We

Fd. BRASS cap bent over & Buried

out of position. No trace of New

BT Recorded in Ren. # 169. We set

New BRASS cap MKd. "COUNTY

SURVEYOR'S OFFICE 1965 T295

$\frac{1}{4}$ 53 | 52 R4W" & MK New BT.

11" W. FIR N. 70° W. 44.5 FT.

Mkd. " $\frac{1}{4}$ 53 CS BT"

BRASS was badly Bent & Buried - &

New B.T. taken out by TRACTOR,

This COR. Located approx. 15° ft.

E. of cat Road ON Edge of

TIMBER.

May 7, 1965

J.W.B.
V.R.T.
M.D.
J.B.

J. W. Ryan

C. S. File No. 52/126-135