

RENEW SOUTH $\frac{1}{4}$ S 5 T 30 S R 3 W
FOUND - ORIG. 18" NOW 24" F
STUMP S 10° E 9.9' SHOWS OLD
BURNED FACE & SMALL BOTTOM
SECTION OF OLD AXED FACE.

NO SCRIBING FOUND, ORIG.
N W BT NOT FOUND.

WE ALSO FIND 1" IRON BOLT
AT COR.

SEE STATEMENT OF T. FLEPPING
ON OTHER SIDE.

SET BRASS CAP AT CORNER
MAD. COUNTY SURVEYORS OFFICE
1963 S $\frac{1}{4}$ S 5 T 30 S R 3 W

NEW BPTS.

37" R. FIR BEARS N 15° E 43.7'

SCRIBED S $\frac{1}{4}$ S C S BT.

NOTE - LOG AT BASE OF BT.

SCRIBED 5° ABOVE GR

11" L.R. FIR BEARS EAST 47.6'

SCRIBED S $\frac{1}{4}$ S 5 C S BT

FEB 19-63

0
+X✓ J.B.

M.D.
B.S.

C.S. File No. 52/138-27

FEB. 19-1963

I T. F. HERRING STATE THAT
I HAVE SEEN SCRIBING ON THE
STUMP USED ON THIS DATE TO
ESTABLISH THE POSITION OF
THE SOUTH ~~W~~ CORNER OF
S 308 R3W. ALSO THAT THE
IRON BOLT FOUND AT THIS CORNER
WAS SET UNDER MY DIRECTION.
T. F. HERRING

DIETZEN NO. 385-6

FILED
RECEIVED

FEB 19 1963

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE