

#44

1/4 Sec. Corner between Sections 18 & 19, T20S R6W WM, Lane County

Here I found one bearing tree, a Fir 32" diam. given in the Gov't. Field Notes as a Fir 22" diam. bearing North 15°West, 25 lks. distant from a small Fir marked for the 1/4 Sec. post. The tree marked for the post has uprooted and slid down the slope so in its place I set a 4" Dogwood post marked 1/4 S C.S., and I marked a new bearing tree:

Red Fir, 42" diam. marked 1/4 S C.S.B.T., bearing South 40°West, 21 lks.

Reset April 11, 1942

R. N. Hinkson

Witnessed by C. L. Foster.

.....

Corner to Sections 17, 18, 19 & 20, T20S R6W, WM, Lane County

145

At this corner I found one original bearing tree, a Fir 12" diam. uprooted but with the marks S19 still plain in the wood. From this tree I set a 4" Dogwood post marked S 17, S 18, S 19 and S 20 C S, and from it I marked four new bearing trees:

Red Fir, 18" diam. marked T20S R6W S17 C.S.B.T., which bears North 38° East, 38 lks.

Red Fir 30" diam. marked T20S R6W S18 C.S.B.T. which bears North 70°West, 47 lks.

Yew 6" diam. marked T20S R6W S19 C.S.B.T., which bears South 47°West, 90 lks.

Red Fir 24" diam. marked T20S R6W S20 C.S.B.T., which bears South 24°East, 54 lks.

Reset April 12, 1942

R. N. Hinkson

Witnessed by C. L. Foster.

.....

1/4 Sec. Corner between Sections 20 & 21, T20S R6W WM, Lane County

Here I found one original bearing tree, a Hemlock now 8" diam. with scribe marks "B T" visible but with the marks "1/4 S" rotted away. The other original bearing tree is down and decayed. From the bearing tree with the marks visible I set a 4" Dogwood post marked 1/4 S 20 and 1/4 S C S and from the post I marked two new bearing trees:

Red Cedar 48" diam. marked 1/4 S C.S.B.T., which bears North 59°East, 83 lks.

Hemlock 24" diam. marked 1/4 S C.S.B.T., which bears North 88°West, 38 lks.

Reset April 21, 1942

Witnessed by C. L. Foster.

R. N. Hinkson

.....