

#31

This survey was made to substantiate the present location of the Section corner common to Sections 23, 24, 25 and 26-23S-3W as sworn to by John F. Woodard in an affidavit filed at the Lane County Court House.

The field work done by Weyerhaeuser Company was under the supervision of Lester Calder, Oregon Registered Engineer, Reg. No. 2149 and the field work done by W. A. Woodard Lumber Co. was by C. A. Randall, Registered Oregon Land Surveyor.

The East 1/2 mile between Sections 23 and 26 and the West 1/2 mile between Sections 24 and 25 were run in August, 1955 by Curtis Price of Weyerhaeuser Company.

The North 1/2 mile between Sections 25 and 26 was run in April, 1956 by M. D. Hale of Weyerhaeuser Co. and R. Herbrandson of Woodard Lumber Co.

The line between Sections 23 and 24 was run in November, 1955 by C. A. Randall of Woodard Lumber Co.

2533

23 24
26 25

Corner common to Sections 23, 24, 25 and 26-23S-3W

GLO Survey Record

A cross (+) at exact corner point upon a large rock 8' high by 25' by 40'. A kind of ledge in small opening or prairie. Found rock ledge but cross (+) apparently eroded away.

24" Fir N 50° E 150 lks. Gone

A mound of stone was erected by Mr. Woodard on the ledge for the corner point. This point was referenced by Marion D. Hale in May, 1956 as follows:

Reference by M. D. Hale (Plates and "W" nails only)
Declination 20°.

26" Fir N 38° E 85.6'

The following accessories were added by Glen McChesney in May, 1958:

Referenced by Glen McChesney (Plates and "W" nails only).
Declination 20°.

14" Inc.Cdr. N 09° W 92.9'
12" Fir S 65° E 36.1'

After this survey was completed, it was quite evident that this corner could be in no other place and still conform to the calls and bearings and distances given in the GLO field notes.

This point has been accepted and is being used by both the Bureau of Land Management and Weyerhaeuser Company for marking the cutting lines around Section 23.

C.S 53/1-33