

253  
#32  
✓

24  
25  
¼ Corner common to Sections 24 and 25-23S-3W

GLO Survey Record

Post		Gone
50" Fir	N 45° W	35 lks. Now a stump - scribing visible.
40" Fir	S 10° E	40 lks. Now a stump - scribing visible.

Set 3/4" x 30 1/2" Monel pipe for corner and set a 2" x 10' pipe alongside the monel pipe.

Referenced by M. D. Hale (Plates and "W" nails only).  
Declination 20°

43" Fir Stp	S 04° W	26.3'	(Original BT)
54" Fir Stp	N 62° W	19.8'	(Original BT)

253  
#30  
✓

23  
26  
¼ Corner common to Sections 23 and 26-23S-3W

GLO Survey Record

4" Chinquapin (corner)		Now 7" and leaning. Axe blaze, but scribing rotted off.
60" Fir	S 30° E	15 lks. Scribing visible
40" Fir	N 13° W	55 lks. Gone

Set 1/2" x 35" galvanized iron pipe for corner in a notch at base of the 7" Chinquapin.

Referenced by M. D. Hale (Plates and "W" nails only).  
Declination 20°.

58" Fir	S 23° E	9.2'	(Original BT)
50" Fir	N 67° E	52.4'	

253  
26  
25

¼ Corner common to Sections 25 and 26-23S-3W

GLO Survey Record.

Post		Original gone - Found Cedar post for corner.
14" Cedar	S 40° W	12 lks. Found
20" Cedar	N 20° W	25 lks. Found

Referenced by Nick Juliano (Plates and "W" nails only).  
Declination 20°

26" Cedar	S 69° W	7.6'
11" Cedar	N 68° E	31.6'

#33  
✓

CS 53/1-34