

35|36  
2|1

Corner common to Sections 35 & 36-21S-4W  
Sections 1 & 2 -22S-4W

Preliminary search did not develop any positive identification of location. Gilbert Gardner in 1955 used the NE rotted stump and SE rotted stump as original BTs and used this location for proportioning to the North. He noted on the map filed in office of County Surveyor that these were green trees. Undoubtedly erroneous. He left no marker for the corner and this would explain his record length for the South line of SW $\frac{1}{4}$  Sec.36-21S-4W as 2707.5 and ours as being 2694'.

There is a 54" Incense Cedar which bears S 49° W 104' from corner and is scribed CS. There is no record in County Surveyor's office.

To substantiate the location here used, in addition to the perfect fit for bearings and distances to the rotted stumps, the following record was made:

From Re-established Corner

GLO record	106' South to Creek	-	WCo. measurement	108'
" "	710' South	" "	" "	719'
" "	1,270' South	" "	" "	1,282'
" "	173' North	" "	" "	180'
" "	132' East	" "	" "	253'
" "	1,056' East	" "	" "	1,222'
" "	1,320' East	" "	" "	Ridge
" "	2,112' East	" "	" "	2,170'
" "	2,112' West	" "	" "	2,110'

NOTE:- GLO record to creeks East are to even chains and could indicate estimated distances.

35|36  
2|1

Corner common to Sections 35 & 36-21S-4W  
Sections 1 & 2 -22S-4W

GLO Survey Record

Post		Not Found
7" Fir	16 lbs	No evidence.
8" Fir	71 lbs	Rotted remains of a fir stump.
23" Fir	S 62° E 120 lbs	Rotted remains of a fir stump.
12" "	N " 45 "	No evidence.

Set Wood pipe for corner from rotted stump 11° E 120 lbs and from rotted stump S 62° E 120 lbs.

Referenced by Glen McChesney (Weyerhaeuser Method)  
Declination 25°

11" Fir	S 67° E	6.5'
57" Cedar	S 6° E	25.8'
19" Fir	S 69° W	42.2'
11" Fir	N 55° W	12.0'

26 copies