

Referenced by Glen McChesney (Weyerhaeuser Method)
Declination 20°

12" Red Ced.	N 32° E	22.0'
50" Fir	S 79° E	39.9'
32" R.Ced.Stp	S 02° W	31.4'
66" Fir	N 45° W	28.6'

36
1

¼ Corner common to Section 36-22S-4W
Section 1-23S-4W

2350

GLO Survey Record

Post			Gone
17" Fir	N 22° E	26 lks	38" Fir windfall - faces are up, filled with dirt and upper face rotted.
28" Fir	S 57½° W	70 lks	Remains of roots of large Fir S 58° W - 46.2'

Found 1" iron pipe 6" out of ground for corner good for distance and bearing from GLO Bearing Trees. Drove 1" x 30" aluminum pipe beside this iron pipe.

Referenced by Glen McChesney (Plates and "W" nails only)
Declination 20°

26" Fir	N 71° W	11.9'
50" Fir	S 75° W	15.6'

35 | 36

¼ Corner common to Sections 35 and 36-22S-4W

2351

GLO Survey Record

Post and Stone			Original not found
14" Cedar	N 60° W	21 lks	36" Incense Cedar-Scribing visible
5" Spruce	S 40° E	45 lks	Gone (Probably meant White Fir)

Found mound of stone around post for corner not original, good for distance and bearing from NW Bearing Tree.

Referenced by Glen McChesney (Plates and "W" nails only)
Declination 20°

14" Fir	N 89° E	10.2	
36" I.Cedar	N 60° W	13.1	(Original BT)

CS 53/1-52