

Replacement of $\frac{1}{4}$ Corner between Sections 33 & 34,
T2LS, R3W, WM

Beginning at NW corner of Sec. 34, T2LS, R3W, WM, said point being determined from USED boundary monuments being 666.5 feet West of USED Monument S 27-12,

Run thence South $0^{\circ}39'$ East 5264.2 ft. to the SW corner of said Sec. 34, said corner being marked by a 2" iron pipe, two original Cedar bearing trees standing.

At halfway between said section corners, I set 2" iron pipe 40" long, 2" above ground for the $\frac{1}{4}$ Corner between said Sections 33 & 34, marked new bearing tree, 8" Douglas Fir which bears North 47° East 58.5 ft, which I marked "1/4S".

Neither of the original bearing trees for this corner were found.

Dec. 21, 1953.

Present: Robert Barta

/s/ Gilbert A. Gardner

.....

Replacement of $\frac{1}{4}$ Corner between Secs. 24 & 25,
T2LS, R4W, WM

Start at NE corner of Sec. 25; run South $89^{\circ}21'$ West 5330.5 ft. to the NW corner of said Sec. 25.

At a point halfway between said Sec. Corners, find old stump of Fir 24" when scribed, now 40"; chopped out lower part of stump and find "B" plainly visible.

From this BT at a point North 40° West 16.5 ft. as described in original field notes, set 2" iron pipe 48" long.

Marked 50" Douglas Fir which bears North 17° East 20.0 ft. and a 17" Douglas Fir which bears South 20° East 26.5 ft.

From this point the NE corner of Section 25 bears North $89^{\circ}20'$ East 2671.35 ft. and the NW corner of Sec. 25 bears South $89^{\circ}22'$ West 2659.15 ft.

Dec. 16, 1953.

Present: Robert Barta.

/s/ Gilbert A. Gardner

.....

63 ✓

CS 53/1-64