

T21S, R4W, WM

Sec. Cor. common to Secs. 26, 35, 34 & 27

Sec. Cor. found with these BTs, set by original gov't. survey

24" Fir S 68°W 11.9 ft. (alive)

30" Fir N 86°E 23.8 ft. (alive)

40" Fir S 8½°E 23.8 ft. (alive)

of NW ¼

1/16 Cor./on N. side Sec. 25

Set BTs & 2" iron pipe

10" D. Fir brs. S 35°E 64.2 ft.

10" D. Fir " S 9°W 60.0 ft. marked 1/16 S BT

¼ Cor. on N. side Sec. 25 (also S. side Sec. 24)

¼ Cor. Found 1 BT 24" Fir S 40°E 16.5 ft.

Set 2" iron pipe 48" long marked new BTs

50" D. Fir N 17°E 20.0 ft.

17" D. Fir S 20°E 26.5 ft. marked ¼ S BT

Sec. Cor. common to Secs. 25 & 36, T21S, R4W, and Secs. 30 & 31, T21S, R3W,

Sec. Cor. found with these BTs; set by original gov't. survey

16" Fir S 73°E 9.9 ft. now stump

16" Fir N 63°W 13.2 ft. now 28"

No other BTs located

Set 1" steel pin

¼ Cor. S. side Sec. 25 and N. side Sec. 36

Set ¼ S. stake 4"x4"x3'

2 new BTs - 10" D. Fir N 23°W 39.0 ft.

12" Alder S 16°E 38.5 ft. marked ¼ S BT

set at proportional distance

¼ Cor. E. side Sec. 36 & W. side Sec. 31

¼ Cor. found with these BTs set by original gov't. survey

12" I. Cedar N 15°E 13.9 ft. (now dead)

10" Laurel gone

Fence running North and South from Big Yew post

¼ Cor. S. side Sec. 36

¼ Cor. found with these BTs set by original gov't. survey

18" Fir N. 31°E 13.2 ft. now 28" standing

40" Cedar S 10°W 48.2 ft. now blown down

Sec. Cor. SW Cor. Sec. 36

Sec. Cor. found with these BTs; set by original gov't. survey

20" Fir S 62°E 79.2 ft. now 32" (alive)

8" Fir N 11°E 46.9 ft. now 20" (alive)

No other BTs located

*This is no good
reset by Gov't & Weyerhaeuser
See Restoration by Calder
3-7-58
JEW*

¼ Cor. W. side Sec. 36

Set ¼ S stake 4"x4"x3'

2 new BT - 18" D. Fir S 76½°W 64.5 ft.

12" Alder N 52°E 19.5 ft. marked ¼ S BT

set at proportional distance

CS 53/11-68