

T19S, R4W, WM, Oregon

Restored the 1/4 Cor. bet. Secs. 34 & 35. Post gone.

Red Fir 24" diam. when marked brs. S 68°W 24 lks. dist. is gone except the bark shell of the old stump.

Red Fir 6" diam. when marked brs. S 30°E 24 lks. dist. is now 30" diam. markings overgrown but scars are plain.

Set a post for 1/4 Sec. Cor. marked 1/4 S CS

Marked the original bearingtree now 30" diam. brs. S 30°E 24 lks. dist. 1/4 S BT CS

Red Fir 36" diam. brs. S 9°W 65 lks. dist. marked 1/4 S BT CS

/s/ Frank A. Tripp

July 2, 1935.

Deputy County Surveyor

T20S, R5W, WM, Oregon

Restored the 1/4 Cor. bet. Secs. 35 & 36 Post gone.

Fir bearing tree 6" diam. when marked brs. N 23°E 16 lks. dist. is now a 12" six foot snag, has been chopped out and markings are plain.

Fir bearing tree 6" diam. when marked, brs. S 28°W 17 lks. dist. is now a 10" sixteen ft. snag markings overgrown.

Set an Oak post for the 1/4 Sec. Cor. marked 1/4 S CS, from which

Fir 24" diam. brs. N 35°W 18 lks. dist. marked 1/4 S BT CS

Fir 20" diam. brs. N 61°E 28 lks. dist. marked 1/4 S BT CS

Present: H. S. Addison
J. K. Addison
H. W. Gibson

/s/ Frank A. Tripp

July 22, 1935

Deputy County Surveyor

CS 53/1-82