

REN. T24SR4W  $\frac{1}{4}$   $\frac{S9}{S16}$

AT COR. FD.  $\frac{3}{4}$ " IRON PIPE  
DRIVEN FLUSH WITH GROUND.

FD. MAPLE TREE (NOW 26" DIAM.)

N  $19^{\circ}$  W 9<sup>2</sup> FT. - OPENED SEVERAL  
YEARS AGO. - FD. 2 OLD FACES - UPPER  
& LOWER - SURFACE ROTTED - NO SCRIBE  
MKS. FD. - CALL ON CREEK IN GOVT NOTES  
APPROX. 15 FT. MORE THAN PRESENT DIST. -  
FD. CEDAR STAKE ROTTED OFF. - CRUISER'S  
MKS ON SMALL CEDAR NEAR COR. - FITS  
GOOD FOR LINE BET. SEC. CORNERS.  
NO TRACE OF ORIG. S.W. B.T. FD.

ALONGSIDE IRON PIPE AT COR.  
SET IRON PIPE WITH BRASS CAP MKD.  
"COUNTY SURVEYOR'S OFFICE 1963

T24SR4W  $\frac{1}{4}$   $\frac{S9}{S16}$

BLAZE & SCRIBE 2 NEW TREES:

6" INCENSE CEDAR S  $36^{\circ}$  W 17<sup>3</sup> FT.

MKD. "  $\frac{1}{4}$  S 16 CS BT "

6" INCENSE CEDAR N  $45^{\circ}$  E 29<sup>7</sup> FT.

MKD. "  $\frac{1}{4}$  S 9 CS BT "

FEB. 15, 1963

M.G.

V.T.

M.S.

Milo E. Coffey

C.S. File No. 53/9.27