

REN. T24SR4W MOST EASTERLY
S.E. COR. D.L.C. #41

FD. SPLINTERED FIR STUMP (NOW

60" DIAM.) S79°E 124 1/2 FT. (SLOPE DIST.) -

FD. GOOD REVERSE SCRIBING "BT"

FD. FIR STUMP (NOW 50" DIAM.) N71°E

166 3/4 FT. (SLOPE DIST.) - CUT OPEN &

FD. GOOD SCRIBING "T"

FD. 2 FIR STUMPS NEAR CORNER -

BOTH WITH SCRIBING "BT" WHICH I
ASSUME WERE MARKED BY ROBERTS IN 1904 -

HOWEVER NEITHER OF THEM FITS CORNER AS
SET. NO COMBINATION OR JUGGLING OF
BEARINGS & DISTANCES AS RECORDED BY
ROBERTS WOULD MAKE IT POSSIBLE TO SET
A CORNER FROM THESE STUMPS.

AT COR. SET IRON PIPE WITH BRASS

CAP MKD. COUNTY SURVEYOR'S OFFICE

1963 T24SR4W ESE DLC 41 1"

BLAZE & SCRIBE NEW TREES!

16" DOUGLAS FIR N43 1/2°E 123 1/2 FT.

MKD. "ESE DLC 41 CSBT"

14" DOUGLAS FIR N77°E 82 1/2 FT.

(88 FT. ON 20° SLOPE) MKD. "ESE DLC 41 CSBT"

CORNER LIES ON VERY STEEP N.W. SLOPE.

Milo C. Godfrey

APR. 12, 1963

M.G.
V.T.
M.S.

NOT FD. - N.E. COR. D.L.C. #41

C.S. File No. 53/9-58

Re #10

Q X ✓