

Renew South $\frac{1}{4}$ COR. 532 - 8014 T31-14

of T315 RIW, Ed. 2⁺ COR. SNAG

of one BT in place, other BT Turned
out & out of place, $\frac{1}{2}$ " I.P. Pulled out
& lying at approximate COR.

10" Now 12" W. FIR (SNAG) N. 10° W. 16⁵ ft

Shows " $\frac{1}{4}$ 532 CS BT" scribe - This

SNAG 6ft. Tall. This B.T. Recorded

in Renewal # 5. We set 1" I.P.

& BRASS Cap MKd. "COUNTY SURVEYORS

OFFICE 1964 T315 RIW

~~32~~ " & MK New BTs -
T325

9" W. FIR N. 78° E. 54² ft.

Mkd. " $\frac{1}{4}$ 532 CS BT"

12" D. FIR N. 48° W. 58⁰ ft.

Mkd. " $\frac{1}{4}$ 532 CS BT"

This COR. Lies 165⁰ ft. East

of the Closing COR. of Sections

5 & 6 of T315 RIW

Dec 15, 1964

U.R.T.
M.D.
J.B.

OR
+X

U.R.T. Roy

C. S. File No. 53/15-14

#2


Section 32

Twp 31

Rge 1

N

Date: 2/5/64



How was corner identified? ONE SNAG B.T.

Condition of corner: POOR

Best route to reach corner: SEE CARD #1

Other Remarks:

Quadrant	NE	NW	SE	SW
Species & Size				
Dist. & Bearing				
Condition of Scribe	<u>Good</u>			
Original or Resurvey				
Appearance of B.T.				
Tags, Nails, etc.				

Jeff E. Clark
Signed