

Review $\frac{1}{4}$ S 2 | S 1 T 315 R 9W

Ed. at $\frac{1}{4}$ cor. Both BT's alive & standing

& VERR old Yew Post, Rotted Badly.

8" Now 16" FIR S. 45° W. 30 $\frac{1}{2}$ FT.

open & shows " $\frac{1}{4}$ " scribe.

6" Now 8" chinquapin S. 45° E 28 $\frac{1}{2}$ FT.

Recorded as S, 50° E. Shows good SCAR.

Set 1" I.P. & BRASS Cap at intersection

of slope distances & Bearing to FIR

BT. - MKD "COUNTY SURVEYOR'S OFFICE

1964 T 315 R 9W $\frac{1}{4}$ S 2 | S 1"

& MKD New BT's -

7" Hemlock N. 67° E 20 $\frac{1}{2}$ FT.

MKD " $\frac{1}{4}$ S 1 CS BT"

8" Hemlock S. 78° W. 29 $\frac{1}{2}$ FT.

MKD " $\frac{1}{4}$ S 2 CS BT"

This cor. lies approx. 75° ft.

South of DRY CREEK Bottom on

steep North slope.

Oct. 6, 1964

V.R.T.

M.D.

J.B.