

RENEW $\frac{1}{4}$ COR $\frac{208}{63}$ T 31 S R 9 W

FOUND - STONE AT CHECKS
FOR SIZE MARKINGS NOT FD.
WE ALSO FIND 40" NOW 40"
FIRST ^{STAKE} N 10° E 30' SHOWS GOOD
SCRIBING "BT" ON BT NOT
FOUND.

SET BRASS AND AT CORNER
MIKE COUNTY SURVEYORS
OFFICE 1963 $\frac{1}{4}$ S 28
T 31 S R 9 W

NEW BTO.

6" LAUREL BEARS N 65° W 37'
SCRIBED $\frac{1}{4}$ S 28 C 2 BT

20" R.F.R. BEARS SOUTH 61'
SCRIBED $\frac{1}{4}$ S 33 C 2 BT

MAY 28 - 1963

H.P.
B.D.
B.S.

MAY 20 1963

+

DIETZEN NO. 388-6

Section 28

Top 31 S

Ree 2

N

Date: Sept. 4, 1962



How was corner identified By rocks and B.T.s

Condition of corner: Fair

Best route to reach corner: Follow Rkt. Dollar's road up

West Fork of Cow Crk. to line Xing rd. on East side of road then approx. 2 1/2 tallies west to cor.

Other Remarks:

South line of sec. 28 has been retraced in approx. 1959

Brushed line has not grown up much and is easy to follow.

Paul L. Litchford
Signed

Quadrant	NE	NW	SE	SW
Species & Size	<u>Fir 42"</u>		<u>Fir 78"</u>	
Dist. & Bearing..	<u>N18°E 33'</u>		<u>S75°E 277'</u>	
Condition of Scribe	<u>Mostly burned off</u>		<u>Mostly rotted off</u>	
Original or Resurvey	<u>Orig.</u>		<u>Orig.</u>	
Appearance of B.T.	<u>Dead</u>		<u>Fell over and slid down hill</u>	
Tags, Marks, etc.				