

RENEW 28/27 T30S R5W  
38/24

FD - 2" I.P. AT COR FALL  
AS RECORDED EXCEPT WE  
DO NOT FIND SW BT.

NEW BT

6 LAUREL BEARS S 81° W 37.0  
SCRIBED 533 T30S R5W C 5 BT

SET 15 - 1963  
D.T.  
M.D.

Ren. #

+ X V O

RENEW 1/4 COR 11/12 T30S R5W

FOUND - 1/2" I.P. 3" UNDER ORIG 7"

NOW 24" FIR S 43° E 5.2 TELL BT

NOW FACE DOWN. WE ALSO FIND

ROTTED BASE OF LARGE OAK THAT

CHECKS FOR ORIG. SW BT

SET 3/4" I.P. ALONGSIDE I.P.

NEW BT.

9" R. FIR BEARS S 73° W 21.5

SCRIBED 1/4 S 11 C 5 BT

10" LAUREL BEARS S 68° E 54.5

SCRIBED 1/4 S 12 C 5 BT

Ren. # 112

+ X V O

C. S. File No. 53/26-10

DIETZEN NO. 385-6