

Renewal #207 ^{INT.} D.L.C. #63 Sec 30 T305 R5W

Found:

11" cedar now 12" S85 1/2 E 167"
 scribe visible INT & CT BT

Power Pole C 8377 S83W (Rec S85W) 81"

No Trace of 18" W.P.O.K. N35W Due to Rd.

I do not find ^{3/4"} I find 95" it seems to be buried under large Back Fill (Rocks too large to move)

Renewal

Using 1 Bearing S85 1/2 E + Intersection of Two Dist. I set Brass cap at D.L.C. cor. M.K.D.

County Surveyors Office

T305 R5W

INT.	D.L.C.
1.	#63

1971

Note: This cor lies 70° West of County Rd. + 180 North of Drive Way

7-29-71

O.K.
 J.W. O.

[Handwritten signature]

#251

C.S. File No. 53/26-50

DIETZEN NO. 385-6