

Revised

RENEW $\frac{1}{4}$ COR. $\frac{22}{27}$ T 30 S R 4 W

FOUL - BOTH OKG. BTS 15" NOW
20" R. FIR N 38° E 10.5 WE. OPEN &

FIND GOOD Scribing. OKG. 24"

NOW 25" R. FIR S 15° W 25.1 SHOWS

GOOD BARK Scribing.

SET BRASS CAP AT CORNER

MAD. COUNTY SURVEYORS OFFICE

1963 $\frac{1}{4}$ S 22 T 30 S R 4 W
527

REPLACE NOW 20" R. FIR N 38° E

11.5' $\frac{1}{4}$ S 22 CS BT

DIETZEN 140 2085

NOTE - THIS COR WAS RENEWED
BY BOYER 1971. RECORDED STATE
THAT HE FOUND A BT DESCRIBED
1854 SURVEY. WE DO NOT FIND
EVIDENCE OF THIS BT.

SURVEYOR DID NOT FIND BTS. AS
RECORDED SO SET NEW COR. &
NEW BTS.

WE FIND BOYERS NEW BT

20" R. FIR WHICH IS BARK SCRIBED
 $\frac{1}{4}$ S 22 CS BT. BEARS N 56° E 25.6
FROM TRUE COR.

NOTE - COR IS ON TOP OF

XX COURSE N 2. S. FILE No. 53/26-73