

REN. T 27 S R 4 W N $\frac{1}{4}$ S 36 ONLY

FD, CEDAR STUMP (NOW 40" DIAM)

S 35° W 14 $\frac{1}{2}$ FT. - CUT OPEN &
FD. GOOD SCRIBING "B.T"

DID NOT FIND BRASS CAP
SET IN 1917.

DID NOT FIND ANY TRACE OF
S.E. TREE.

AT COR. SET IRON PIPE WITH
BRASS CAP MKD. "COUNTY SURVEYOR'S
OFFICE 1963 T 27 S R 4 W $\frac{1}{4}$ S 36"

RESCRIBE 40" CEDAR STUMP
S 35° W 14 $\frac{1}{2}$ FT. MKD. " $\frac{1}{4}$ S 36 CS"
(OLD "BT" VISIBLE)

BLAZE & SCRIBE!

31" HEMLOCK STUMP N 49° E
4 $\frac{1}{2}$ FT. MKD. " $\frac{1}{4}$ S 36 CS BT"

- NO LIVE TREES AVAILABLE. -

NO OTHER STUMPS AVAILABLE.

OCT. 11, 1963

Milo E. Godfrey

M.G.
W.S.
M.D.
M.S.
J.H.

+ 2

C. S. File No. 53/33