

Renew Standard Cor. of 534/535 T275 T285 R4W

Fd. 1958. B.T. 525 Follows -

12" cedar N. 59° E. 73 <sup>3</sup>/<sub>4</sub> ft.

Now stump & covered by logs -  
scribe visible.

13" now 14" cedar N. 29 <sup>3</sup>/<sub>4</sub>° W. 39 <sup>1</sup>/<sub>2</sub> ft.

alive - scribe visible. we find  
Ead. Brass cap & Pipe pushed over  
& Buried 13" below surface.

we reset Brass cap in proper  
position & mk New B.T. -

6" cedar N. 36 <sup>1</sup>/<sub>2</sub>° E. 136 <sup>8</sup>/<sub>16</sub> ft.

Mkd. "T275 R4W 535 cs BT"

This cor. lies East 39 <sup>3</sup>/<sub>4</sub> ft.  
of closing cor. of sec. 3

3/2 of T285 R4W. Also stump  
of orig. NW. B.T. still in location.

June 23, 1967

V.R.T.  
J.H.  
D.W.

*(Handwritten signature: V.R. Tracy)*

#111

#129-T27-A

OK. J.W.B.

C.S. File No. 4653/3331