

Renew Sec. Cor.

R6W S13 | S18 R5W
524 | 519

T275

Fd. $\frac{1}{2}$ " x $\frac{1}{2}$ " IRON BAR 2.2" Below Surface
of ground & BT as Recorded in Ren.
11 of 27-5 as follows -

30" Now 32" cherry S. $85\frac{1}{2}$ ° E, 255° ft.
shows faint "BT" BARK scribe - Now almost Dead

Other BT's Now gone Due to Floods -

Set 1" I.P. & BRASS cap over IRON BAR

Mkd. COUNTY SURVEYOR'S OFFICE 1966

T275 R6W ^{S13 | S18} 524 | 519 R5W " 6 inches above

ground. & a 8° ft. steel fence post

along side BRASS cap 5° ft. above ground.

Mk. New B.T.

13" B. oak S. 2° E. 159⁷ ft

Mkd. " T275 R5W S19 CS BT "

No other trees close.

Beacon tower on Mnt. Mebo Bears

S. $64\frac{1}{2}$ ° W. & KPIC-TV. Tower on Rose Mtn.

Bears N. $39\frac{1}{2}$ ° E. Cor. lies approx.

100 ft. East of Top of Bank on West

Edge of Elk Island.

June 16, 1966

V.R.T.
J.B.
J.H.

[Handwritten signature]
110-25-113
* 11-

C.S. No. 53/38-12