

Renewal B SE. EX. 2 DAC #39 TRIS B5V1

Found ↓

By using Metal Finder Found 3/4" I.P.R. I (J.M.P.) have tied to Before

15" P.S.B. S 1/2 E 36 7
NOW a Stamp.

Top curb N 89 40W 94 9 Not Found.

Renewal

Without Disturbing St set Reference out 2, cross-s.

Cross on top of curb on West Side of Terrace N 10 E 21 3

Cross on top of curb on East Side of Terrace N 62 E 38 2

2" Iron pipe Initial Point of 15" Adv. top North 113 5 overlook

OK J.W.B.

1-31-68

~~J.W.B.~~
~~J.W.B.~~

DIETZEN NO. 385-6

#123

C. S. File No. 53/38-16