

Renewal

23/24

7713 RSW

Found: (Renewal # 1)

Brass cap at 1/4 cor MKD  
county surveyors office

1/4 cor

23/24

See attached for slip BT. New LR

16" B. Oak New 19" N 81 W 95°  
Shows good scars

12" B. Oak New 14" S 25 E 13°  
Shows good scars

Renewal:

As Road is to be widened I removed said cor and set with cor. as follows:

Set Brass cap for wit. cor Be MKD.

county surveyors office

1/4 cor

7715 RSW

23/24

W.C. 35' south to

1969

New Bearing Tree:

205 Pipe N 17 W 29°  
scribed W.C. 1/4 S 23° as BT

18" B. Oak S 27 E 16°  
scribed W.C. 1/4 S 21° as BT

#135 V. J.W.B.

O.K.E.R.

C.S. File No. 53/38-19 2-7-69

DIETZGEN NO. 385-6

This car lies in N-S  
Fence line.

J.M.P.?

CS 53/38-19

B

Renewal 23/29 = T. 235 R. 5W

Found:

12" B. Oak Now 12" S27E 16"  
Scribe visible 1/4 S 29 CS BT

20" S. Pine Now stump N17W 29"  
Scribing on stump 1/4 S 23 CS BT

Also Brass cap for W. C. Co. M. S. D.  
county surveyors office

T. 235 R. 5W

1/4

S 23 / S 24

Ren # 135

W. C. 35' South to

1969

Renewal

New Bearing Tree

8" Triple Oak S 84 W 31"  
Scribed 1/4 S 23 CS BT

12-19-69

*[Signature]*

O. V.  
J. W. W.

#135

C. S. File No. 53/38-19

DIETZGEN NO. 3886-6