

Renewal $\frac{54}{59} | \frac{53}{910}$ T275 R5W

Found:

24" B. Oak Down S 17 1/2 W 123 1/2
Tree had been opened
Scribe visible "5" O.B.T.

11" Laurel Now 20" N 77 3/4 W 156 1/4
No Scar Visible O.B.T.

9" W. Oak Now 19" S 23 1/2 W 92 1/4
Not Much Scar for Face O.B.T.

8" B. Oak Now N 7 E 52 1/2
I find this bearing to be N 15 E
opened for scribe "3"

Renewed:

Set Brass cap at Sec cor NW
county Surveyors office
T275 R5W

$\frac{54}{59} | \frac{53}{910}$

1966

New Bearing Trees
9" W. oak N 62 W 45 1/2
scribed T275 R5W S 4 CS BT

11" W. oak S 56 E 179
scribed T275 R5W S 10 CS BT
This tree is cor. post for fence
cor. NW W

5" B. oak S 87 W 50 1/2
scribed 59 CS BT

Renewal #46

3-22-66
J. W. B.
C. S.
E. 11/11

* #111

O.K. J.W.B.

C.S. File No. 53/38-23

DIETZGEN NO. 385-6