

Renew  $\frac{1}{4}$   $\frac{522}{527}$  T30S R7W

Fd. at cor. stump of original BT.  
Very badly Rotted:

40" Pine S.  $30^{\circ}$  W.  $3^{\frac{3}{4}}$  ft.

Fd. face with " $\frac{1}{4}$  S" scribe & old ax  
marks. The 10" oak BT. is gone.  
we find an oak down hill with  
center rotted away, we find no scribe.  
we set 1" I.P. & BRASS cap MKd.

"COUNTY SURVEYORS OFFICE 1965  
T30S R7W  $\frac{1}{4}$   $\frac{522}{527}$ " & MK. New  
B.T.'s —

10" D. FIR S.  $43^{\circ}$  E. 6<sup>0</sup> ft.

Mkd. " $\frac{1}{4}$  S 27 CS BT"

15" D. FIR. N.  $46^{\circ}$  W. 15<sup>8</sup> ft.

Mkd. " $\frac{1}{4}$  S 22 CS BT"

This cor. is approx. 300<sup>0</sup> ft  
west of Ridge top.

March 10, 1965

FILED

RECEIVED

VRT  
MD,  
J.B.

MAR 10 1965

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

C. S. File No. 53/40-65

XO #16  
X