

Renew $\frac{1}{4}$ $\frac{521}{528}$ T305 R7W

Fd. Both ORIGINAL B.T.'s as follows -

7" Now 7" Laurel S. 20° W. 3³ ft.

Down & Badly Rotted - find old Face
Scribe Rotted away.

8" Now 9" Laurel N. 25 E. 9³ ft.

Down & upper Face Rotted Badly - find

"B" scribe on lower Face in poor

condition. Set 1" I.P. & BRASS CAP

Mkd. "COUNTY SURVEYORS OFFICE

1965 T305 R7W $\frac{1}{4}$ $\frac{521}{528}$ " & MK.

New B.T.'s -

22" D. FIR S. 34° W. 9⁴ ft.

Mkd. " $\frac{1}{4}$ S 28 CS BT"

24" D. FIR N. 55° E. 6⁶ ft.

Mkd. " $\frac{1}{4}$ S 21 CS BT"

This COR. Lies on side hill

Sloping S. 16° E.

April 28, 1965

V.R.T.
M.D.
J.B.

FILED

RECEIVED

APR 28 1965

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

C. S. File No. 53/40-67