

Review $\frac{1}{4}$ 529/528 T305 R7W

Fd. at the location of CORNER 2 Stone
12" x 11" x 5" Badly chipped - No marks fd.
Recorded To be 12" x 12" x 10". 2N BT as
follows. -

ORIG. 10" Now 11" L24Ac / N. 70° E. 14 $\frac{1}{2}$ Ft.

TURNED out & dead. - upper SCAR badly Rotted

Lower SCAR heeled over - we open &

find. "BT" & AXE notch. We find only

a hole where other BT should have been.

We set 1" IP & BRASS cap MKD. "COUNTY

SURVEYOR'S OFFICE 1965 T305

$\frac{1}{4}$ 529/528 R7W " & MK. New BTs -

6" Hemlock N. 22° E. 5 $\frac{1}{2}$ Ft.

MKD. " $\frac{1}{4}$ 528 CS BT"

14" D. Fir N. 68° W 17° Ft.

MKD. " $\frac{1}{4}$ 529 CS BT"

CORNER lies 50° Ft West of top
of Bluff 75° Ft. hi approx.

July 1, 1965

FILED

RECEIVED

W.R.T.
D.
T.C.

JUL 1 1965

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

C. S. File No. 53/40-83